

100-443886-100




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7





FIG. 8



9/13

FIG. 9
Effect of Carbon Monoxide Treatment of Preform in Core Consolidation on Optical Fiber
Hydrogen-Induced Attenuation




FIG. 10





FIG. 11





FIG. 13



- 1200ppm CO in Ramp and Dope w/outgas
- 1200ppm CO in Ramp Dope and Sinter
- * 1200ppm CO in Ramp and Dope
- Standard without CO

FIG. 12




FIG. 14

140

